


How to fit your N95 mask

1. Hold respirator in hand with molded nose contour (narrow end) at fingertips, allowing head straps to fall below hand.



2. Place respirator under chin with molded nose contour (narrow end) up



3. Pull shorter bottom strap overhead, below ears, to around neck. Raise longer top strap to top back of head. Adjust respirator for comfortable fit.



4. To check fit, cup both hands over respirator and exhale deeply. If air leaks at respirator edges, adjust straps back along the sides of the head.

